

Thomas Mendenhall House
N. W. Cor. Front and Walnut Streets
Wilmington, Delaware

HABS No. Del- 21

HAB
DEL.
2- WILM
9.

PHOTOGRAPHS
WRITTEN HISTORICAL AND DESCRIPTIVE DATA
District of Delaware

Historic American Buildings Survey
Weston H. Blake, District Officer
909 West Street, Wilmington, Delaware

x

HABS
DEL.

2 - WILM

9 -

THOMAS MENDENHALL HOUSE
Wilmington, New Castle County, Delaware

Owner: Delaware Chemical Company, Wilmington, Delaware

Date of Erection: Beginning 19th Century

Builder: Thomas Mendenhall


Present Condition: Very Dilapidated

Number of Stories: Three

Materials of Construction: Brick. Flemish Bond. Brick belt course at second and third floor lines. Fine doorway, original wainscoating. First floor greatly remodelled. Original sash second and third floors.

Other Existing Records: Offices of Recorder of Deeds and Register of Wills of New Castle County.

Additional Data: This is one of the better class and larger city residences of the period. Of especial interest is the chimney in the center of the ridge instead of on the usual gable wall.


District Officer

Rev. Jan. 21 '37 - TW